

#### MLS # 73434926 - New Single Family - Detached

23 Adele Avenue List Price: **\$569,000** 

Haverhill, MA 01832

**Essex County** 

Style: Ranch Total Rooms: 6 Color: Tan Bedrooms: 3 Grade School: Bathrooms: 1f 0h

Middle School: Main Bath: High School: Fireplaces: 2

Approx. Acres: 0.28 (12,327 SqFt) Approx. Street Frontage:

Handicap Access/Features:

Directions: Rte 97 or Rte 113 to Lowell Ave to Adele Ave

Welcome to this beautiful single-level home! Step inside to a spacious living room featuring hardwood floors, a woodburning fireplace and an oversized bay window which fills the space with natural light. Flow seamlessly into the updated eat-in kitchen, complete with ample cabinetry, granite countertops and newer stainless steel appliances. Enjoy direct access to a large deck overlooking the landscaped yard or relax in the attached sunroom. Down the hall are three generously sized bedrooms with hardwood flooring and large closets; as well as a stunning full bathroom featuring double sinks and a walkin tiled shower. The two-car garage provides excellent storage, and the lower level offers additional expansion possibilities with a second fireplace, workshop area, and abundant storage space. Recent updates include a new boiler, newer windows, and more. Nestled on a quiet dead-end street yet close to highways, shopping, restaurants and everything Haverhill has to offer!

#### **Property Information**

Approx. Living Area Total: 1,383 SqFt Living Area Includes Below-Grade SqFt: No Living Area Source: Public Record

Approx. Above Grade: 1,383 SqFt Approx. Below Grade:

Living Area Disclosures:

Cool Zones: 1 Wall AC Heat Zones: 1 Hot Water Baseboard, Gas

Parking Spaces: 4 Off-Street, Paved Driveway Garage Spaces: 2 Attached, Side Entry

Disclosures: Vermiculite and asbestos have been professionally removed. Sunroom windows will need replacement.

#### **Room Levels. Dimensions and Features**

Room	Level	Size	Features
Living Room:	1	26X15	Fireplace, Ceiling Fan(s), Flooring - Hardwood, Window(s) - Bay/Bow/Box
Dining Room:	1	12X10	Flooring - Hardwood
Kitchen:	1	21X18	Ceiling Fan(s), Flooring - Hardwood, Pantry, Countertops - Stone/Granite/ Solid, Deck - Exterior, Stainless Steel Appliances
Main Bedroom:	1	13X12	Ceiling Fan(s), Closet, Flooring - Hardwood
Bedroom 2:	1	13X11	Ceiling Fan(s), Closet, Flooring - Hardwood
Bedroom 3:	1	12X11	Closet, Flooring - Hardwood
Bath 1:	1	12X6	Bathroom - Full, Bathroom - Tiled With Shower Stall, Flooring - Stone/ Ceramic Tile, Countertops - Stone/Granite/Solid, Double Vanity
Laundry:	В		•
Bonus Room:	1	17X12	Skylight, Flooring - Laminate, Balcony / Deck, Main Level, Exterior Access

#### **Features**

Appliances: Range, Dishwasher, Disposal, Microwave, Refrigerator,

Washer, Dryer

Area Amenities: Public Transportation, Shopping, Park, Walk/Jog Trails, Golf Course, Medical Facility, Laundromat, Highway Access, House of Worship, Public School, T-Station

Basement: Yes Full, Interior Access, Bulkhead, Sump Pump, Concrete Floor, Unfinished Basement

Beach: No

Construction: Frame **Electric: Circuit Breakers** 

#### Other Property Info

Disclosure Declaration: No

Exclusions: Workshop cabinets and kayak rack excluded. (workshop counters remain)

Home Own Assn: No. Lead Paint: Unknown UFFI: Warranty Features:

Year Built: 1962 Source: Public Record

Year Built Description: Actual

Year Round: Yes

Short Sale w/Lndr. App. Req: No

Exterior: Vinyl

Exterior Features: Porch - Enclosed, Deck - Wood

Flooring: Laminate, Hardwood, Parquet

Foundation Size:

Foundation Description: Poured Concrete

Hot Water: **Natural Gas** Insulation: **Unknown** 

Interior Features: Cable Available, Internet Available - Fiber-Optic

Lot Description: **Level** Road Type: **Public** 

Roof Material: Asphalt/Fiberglass Shingles

Sewer Utilities: City/Town Sewer Utility Connections: for Gas Range Water Utilities: City/Town Water

Waterfront: No

Lender Owned: No

#### **Tax Information**

Pin #:

Assessed: \$518,300

Tax: **\$5,550.99** Tax Year: **2025** Book: **37605** Page: **605** 

Cert:

Zoning Code: **RES** Map: Block: Lot:

#### **Office/Agent Information**

Listing Office: Foundation Brokerage Group [ (800) 983-1945

Listing Agent: The Nancy Dowling Team (978) 314-4003 Team Member(s):Nancy A. Dowling (978) 314-4003

Sale Office: Sale Agent:

Listing Agreement Type: Exclusive Right to Sell

Entry Only: **No**Showing: Sub-Agency:

Showing: Buyer's Broker: Lock Box, Schedule with ShowingTime or Call 888-627-2775
Showing: Facilitator: Lock Box, Schedule with ShowingTime or Call 888-627-2775

Special Showing Instructions:

#### **Firm Remarks**

Please send all offers to nancydowlingre@gmail.com in one PDF not through Dotloop.

#### **Market Information**

Listing Date: 9/24/2025 Listing Market Time: MLS# has been on for 0 day(s)

Days on Market: Property has been on the market for a total of **0** day(s) Office Market Time: Office has listed this property for **0** day(s)

Expiration Date: **3/24/2026**Cash Paid for Upgrades:
Original Price: **\$569,000**Seller Concessions at Closing:

Off Market Date: Sale Date:


The information in this listing was gathered from third-party sources including the seller and public records. MLS Property Information Network, Inc., and its subscribers disclaim any and all representations or warranties as to the accuracy of this information. Content @2025 MLS Property Information Network, Inc.







































































































TOTAL: 1383 sq. ft

BELOW GROUND: 0 sq. ft, FLOOR 2: 1383 sq. ft

EXCLUDED AREAS: STORAGE: 317 sq. ft, UNDEFINED: 53 sq. ft, UTILITY: 89 sq. ft,

WORKSHOP: 170 sq. ft, BASEMENT: 832 sq. ft, FIREPLACE: 19 sq. ft,

GARAGE: 414 sq. ft, SCREENED PORCH: 197 sq. ft, PORCH: 46 sq. ft,

DECK: 343 sq. ft, WALLS: 214 sq. ft







TOTAL: 1383 sq. ft

BELOW GROUND: 0 sq. ft, FLOOR 2: 1383 sq. ft

EXCLUDED AREAS: STORAGE: 317 sq. ft, UNDEFINED: 53 sq. ft, UTILITY: 89 sq. ft,

WORKSHOP: 170 sq. ft, BASEMENT: 832 sq. ft, FIREPLACE: 19 sq. ft,

GARAGE: 414 sq. ft, SCREENED PORCH: 197 sq. ft, PORCH: 46 sq. ft,

DECK: 343 sq. ft, WALLS: 214 sq. ft







TOTAL: 1383 sq. ft

BELOW GROUND: 0 sq. ft, FLOOR 2: 1383 sq. ft

EXCLUDED AREAS: STORAGE: 317 sq. ft, UNDEFINED: 53 sq. ft, UTILITY: 89 sq. ft,

WORKSHOP: 170 sq. ft, BASEMENT: 832 sq. ft, FIREPLACE: 19 sq. ft,

GARAGE: 414 sq. ft, SCREENED PORCH: 197 sq. ft, PORCH: 46 sq. ft,

DECK: 343 sq. ft, WALLS: 214 sq. ft



# SELLER'S STATEMENT OF PROPERTY CONDITION #700 (Page 1 of 8)



THIS FORM IS TO BE COMPLETED BY THE SELLER. THE SELLER(S) AUTHORIZES THE BROKER OR SALESPERSON(S) TO PROVIDE THE FOLLOWING INFORMATION TO PROSPECTIVE BUYER(S). THIS INFORMATION IS BASED UPON THE SELLER'S KNOWLEDGE, BUT IS NOT INTENDED AS A GUARANTEE OF THE CONDITION OF THE PROPERTY OR THE CONTINUED SATISFACTORY OPERATION OF ANY SYSTEM. THE BUYER(S) SHOULD INDEPENDENTLY VERIFY ALL INFORMATION BEFORE PURCHASE.

	rty Address 23 ADELE AVE	HAL	IERH	11L, MA		
	(s)/Owner(s) WALTER BENHAY	$\sim$				
How lo	ong owned Zolq How long o	ccupied	201	9	Ap	proximate Year Built 1962 4/-
LTIT	LE/ZONING/RUIL BING INCORNATION					
1. 111	LE/ZONING/BUILDING INFORMATION	Yes	N.	I Halanaaaa	N/A	
1.	Title Problems or Limitations (for example,	tes	No	Unknown	N/A	Description/Explanation
	deed restriction, lot line dispute, order of conditions):		×			
2.	Easement, Common Driveway, or Right of Way		×			
3.	Zoning Classification(s) of property:					
4.	Has the City/Town issued notice of outstanding violation?					
5.	Have you been advised that current use is nonconforming in any way?		M			
6.	Do you know of any variances or special permits?		X			
7.	During Seller's ownership, has work been done for which a permit was required? If yes, explain.	×				SIDING
7a.	Were permits obtained?	M				
7b.	Was the work approved by an inspector?			×		
7c.	Was a licensed contractor hired? (If yes, provide name of contractor)		×			,
7d.	Is there an outstanding notice of any building code violation?		×			
8.	Have you been informed that any part of the property is in a designated flood zone or wetland?		Ø			
9.	Are there any known water drainage problems? Explain.	M				BASEMENT HAD SOME WHEN DUE WHEN SUMP PUMP PAIER DUE TO NO ELECTRICITY ZYRS
II. SY	STEM AND UTILITIES INFORMATION				****	aso
		Yes	No	Unknown	N/A	Description/Explanation
10.	STORAGE TANK					· · · · · · · · · · · · · · · · · · ·
10a.	Is or Has there ever been an underground storage tank?		风		8	
10b.	If yes, type of tank					
10c.	If yes, is it still in use?					
10d.	If not still in use, was it removed?					
10e.	Storage Tank: Leased Owned (See Hazardous Materials Disclosure Page 8)					
SELLE	R'S INITIALS WB	BUYER	R'S INIT	TALS		



# SELLER'S STATEMENT OF PROPERTY CONDITION #700 (Page 2 of 8)



II. SY	STEM AND UTILITIES INFORMATION (Conti			T		
		Yes	No	Unknown	N/A	Description/Explanation
11.	HEATING SYSTEM				_	•
11a.	Type: GAS HOT WATER					
11b.	Age: / YR					
11c.	Are there any known problems with the heating system? Explain.		2			
11d.	Identify any unheated room or area:					SUN PORCH
11e.	Provide approximate date of last service:					SEPTEMBER 2024
11f.	Provide reason for service:					YEARLY MAINTAINENCE
III. W	ATER, SEWER & OTHER UTILITIES				***************************************	
		Yes	No	Unknown	N/A	Description/Explanation
12.	DOMESTIC HOT WATER					
12a.	Type:					
12b.	Age: 14 YES					
12c.	Are there any known problems with the hot water? Explain.		2			
13.	SEWAGE SYSTEM			L	I	
13a.	Municipal ☐Private Sewer					
13b.	If Private Sewer, describe type of system:					
13c.	Provide Name of Service Company		×			
13d.	Date it was last pumped:					Month Day Year
13e.	Frequency of Pumps:					
13f.	During your ownership has sewage backed up into house or onto yard? Explain.					
13g.	Is system shared with other homes?		Z			
13h.	Was a Title 5 Inspection performed?					
13i.	Date of Inspection:					Month Day Year
13j.	Is a copy of Inspection attached?					
14.	PLUMBING SYSTEM					
14a.	Type: COPPER - PVC					
14b.	Problems? Explain.		2			
14c.	Bathroom ventilation problems? Explain.		12/1			
ELLE	R'S INITIALS _ WB	BUYER	'S INIT	IALS _		

MASSFORMS™ Statewide Standard Real Estate Forms ©1999, 2007, 2015 MASSACHUSETTS ASSOCIATION OF REALTORS®



# SELLER'S STATEMENT OF PROPERTY CONDITION #700 (Page 3 of 8)



III. W	ATER, SEWER & OTHER UTILITIES (Continue	ed)				
		Yes	No	Unknown	N/A	Description/Explanation
15.	WATER SOURCE					
15a.	Public ☐ Private					
15b.	Location BASEMENT					
15c.	Date Last tested:			<u> </u>		Month Day Year
15d.	Report Attached?			9	<b>100</b>	
15e.	Water Quality problems? Explain.			4	百	
15f.	Flow rate:			<u> </u>	ā	(gal. /min.)
15g.	Age of Pump:				100	(32
15h.	Is there a filtration system? If yes, indicate age and type of filtration system.			TEST TO SERVICE STATE OF THE S		Age:
IV. EL	ECTRICAL SYSTEMS & UTILITIES	<del></del>				
		Yes	No	Unknown	N/A	Description/Explanation
16.	ELECTRICAL SYSTEM					
16a.	Problems? Explain.		100			
17.	APPLIANCES					
17a.	STOVE, DW. MICKO WASHER DETER, REFRIGERATOR					
17b.	Problems? Explain.		2			
18.	SECURITY SYSTEM					
18a.	Type: SIMPLI SAFE					
18b.	Age:   YP				ō	~
18c.	Provide Name of Service Company					
18d.	Problems? Explain.					
19.	AIR CONDITIONING	<u> </u>	السا			
19a.	□Central □Window ☑Other. Explain.					THRU WALL
19b.	Problems? Explain.		8			
20.	SOLAR PANELS			-		
	□ Leased □ Owned					
20b.	If leased, explain terms of agreement.					
V B	II DINC/STRUCTURAL INFORMATION					
v. BUI	LDING/STRUCTURAL INFORMATION		T			
21	EQUINDATION(S) AD	Yes	No	Unknown	N/A	Description/Explanation
21.	FOUNDATION/SLAB					
21a.	Problems? Explain.	3				CRACK IN FRONT WALL
ELLEI	R'S INITIALS WA	BUYER	'S INIT	IALS		



# SELLER'S STATEMENT OF PROPERTY CONDITION #700 (Page 4 of 8)



V. BU	ILDING/STRUCTURAL INFORMATION (Conti	nued)				
		Yes	No	Unknown	N/A	Description/Explanation
22.	BASEMENT					
22a.	Problems (select any that apply):  Water Seepage Dampness Other. Explain.					PUMP FAILED BECAUSE OF BLECKICTY OUTDO
22b.	Explain amount, frequency, and location of the problems selected in 22a.				<u>-</u>	1 TIME DURING MY OWNERCHIP
23.	SUMP PUMP					
23a.	If yes to 23, provide age and location.					3 YRS
23b.	Problems? Explain.		2			
24.	ROOF					
24a.	Age:			<u> </u>		UKKUOW M
24b.	Problems? Explain.		8			
24c.	Location of leaks/repairs:					
25.	CHIMNEY/FIREPLACE		1			
25a.	Date last cleaned:			8		Month Day Year
25b.	Problems? Explain.					
25c.	Presence of:  Wood Stove Coal Stove Pellet Stove Gas Stove		\$			
25d.	If yes to 25c, in compliance with installation regulations/code/bylaws?					
25e.	If no to 25d, Explain.					
25f.	Is there any history of smoke/fire damage to structure? Explain.					
26.	FLOORS					
26a.	Type of floors under carpet/linoleum:				<u> </u>	
26b.	Are there any known problems with floors (buckling, sagging, etc.)? Explain.		<b>2</b>			
27.	WALLS					
27a.	Interior Walls: Problems? Explain.					
27b.	Exterior Walls: Problems? Explain.		è			
28.	WINDOW/SLIDING DOORS/DOORS					
28a.	Problems? Explain.			0		
29.	INSULATION			L		
29a.	Does house have insulation?	8				see energy audit.
	R'S INITIALS LIPE	BUYER				The state of the s

# SELLER'S STATEMENT OF PROPERTY CONDITION #700 (Page 5 of 8)



V. BU	JILDING/STRUCTURAL INFORMATION (Conti	nued)		***************************************	****	
		Yes	No	Unknown	N/A	Description/Explanation
29b.	If yes, type:	<b>E</b>			9	FIBERGLASS
29c.	Date Installed: WALLS UNKNOWN					Month Day Year
29d.	Location:					
VI. EI	NVIRONMENTAL ISSUES				-	1
		Yes	No	Unknown	N/A	Description/Explanation
30.	ASBESTOS					
30a.	Is asbestos present in exterior shingles, pipe covering or boiler insulation?		1	78		LINKNOWN ABOUT SHINGLE
30b.	Has a fiber count been performed?					
30c.	If yes to 30b., is copy attached? (See Asbestos Disclosure Page 8)					
31.	LEAD PAINT					
31a.	Is lead paint present?			8		
31b.	If yes to 31a., locations present: (Attach copy of Inspection Reports)					
31c.	If yes to 31a., describe abatement plan/ interim controls, if any:					
31d.	Has paint been encapsulated?					
31e.	If yes to 31d. provide date of encapsulation and by whom.					Month Day Year
31f.	Is Lead Paint Disclosure Form available? If yes attach copy. If no, Explain.					
32.	RADON			***************************************	***************************************	
32a.	Has test for Radon been performed? If yes, attach copy. (See Radon Disclosure Page 7)		a			see malysis.
33.	MOLD					, , ,
33a.	Have you been advised of elevated levels of mold at the Property? Explain.					
34.	INSECTS				***************************************	
34a.	History of Termites/Wood Destroying Insect or Rodent Problems?					
34b.	If yes to 34a., explain treatment and dates:					Month Day Year
	(See Chlordane Disclosure Page 8)					
35.	ENERGY AUDIT					
35a.	Has an Energy Audit been performed? If yes, attach a copy.	<u> </u>				see copy
VII. O	UTDOOR AMENITIES & STRUCTURES					
		Yes	No	Unknown	N/A	Description/Explanation
36.	SWIMMING POOL/JACUZZI					
36a.	Problems? Explain.		<u>®</u>			
36b.	Name of Service Company:					
ELLE		BUYEF	R'S INIT		T	





# SELLER'S STATEMENT OF PROPERTY CONDITION #700 (Page 6 of 8)



		Yes	No	Unknown	N/A	Description/Explanation
7.	GARAGE/SHED/OR OTHER STRUCTURE					
7a.	Problems? Explain.					
III. C	ONDOMINIUM INFORMATION				***************************************	
		Yes	No	Unknown	N/A	Description/Explanation
8.	PARKING					
8a.	Number of Spaces					Spaces
8b.	Of those spaces, identify the number that are:					Number of Spaces:
	□Deeded □Exclusive Easements	$\rightarrow$				Deeded
	Assigned		Ц			Exclusive Easements Assigned
	☐Unassigned or					Unassigned
	☐In Common area					In Common area
9.	CONDO FEES					
9a.	Current monthly fees for Unit are:					
	Are any of the following (39b39g.) included					
	in the monthly fees:				_	
9b.	Heat					
9c.	Electricity				1	
9d.	Hot Water					
Эе.	Trash Removal					
of.	Landscaping					
g.	Snow Removal				$\overline{\Box}$	
).	RESERVE FUND				_	
)a.	Has advance payment been made to a condo					
	reserve fund?		Ц			
Db.	If yes to 40a, how much?					
1.	CONDO ASSOCIATION FUND					
1a.	Is owners' association currently involved in					
	any litigation? Explain.		П			
1b.	Have you been advised of any matter which				/	
	is likely to result in a special assessment or					
	substantially increase condominium fees? Explain.	_	_	_	-	
						L
. RE	NTAL PROPERTY INFORMATION					
		Yes	No	Unknown	N/A	Description/Explanation
2.	UNITS					
2a.	Number of Units:					Units
2b.	Has a unit been added/subdivided since		1			
20.				The state of the s	The same of	11
2c.	original construction?  If yes to 42b., was a permit for new/added					



# SELLER'S STATEMENT OF PROPERTY CONDITION #700 (Page 7 of 8)



IX. R	ENTAL PROPERTY INFORMATION					
		Yes	No	Unknown	N/A	Description/Explanation
43.	RENT					Rent \$/month
43a.	Expiration date of each lease:					Month Day Year
43b.	Any tenants without leases?					
43c.	Is owner holding last month's rent?					
43d.	Is owner holding security deposit?					
43e.	If yes to 43c. and/or 43de., has interest been paid?					
43f.	If security deposit held, attach a copy of Statement(s) of Conditions.					4
43g.	Is there any outstanding notice of sanitary code violation? Explain.					
X. MIS	CELLANEOUS INFORMATION					
		Yes	No	Unknown	N/A	Description/Explanation
44.	Do you know of any other problem which may affect the value or use of the property which may not be obvious to a prospective buyer? Explain.	<b>1</b>				SUN ROOM - WINDOWS AND GLOZING.
XI. DE	ESCRIPTION/EXPLANATION					
D	E SUN ROOM WINDOWS  AMAGE TO TIJE SASH  LL WINDOWS EXCEPT KIT	GAS1	Ket	FAILU	RE	
lealth,	Iowing clauses are provided for descriptive purpose the Massachusetts Department of Environmental Hazard Insurance Disclosure Clause (Question #8) der may require Flood Hazard Insurance as a condition of the lender determines that the property is in a flood hazard.	oses or	nly. For ction, o	E. Radon Disclo Radon is an or ground by the n development of	nation, riate ag sure Cla dorless, ormal de radioaci	
ELLE	R'S INITIALS WB	BUYEF		of developing lu		



# SELLER'S STATEMENT OF PROPERTY CONDITION #700 (Page 8 of 8)



B. Hazardous Materials Disclosure Clause (Question #10)

In certain circumstances Massachusetts law can hold an owner of real estate liable to pay for the cost of removing hazardous or toxic materials from real estate and for damages resulting from the release of such materials, according to the Massachusetts Oil and Hazardous Material Release and Response Act, General Laws, Chapter 21E. The buyer acknowledges that he may have the property professionally inspected for the presence of, or the substantial likelihood of release of oil or hazardous material and such proof of inspection may be required as a prerequisite for financing the property.

C. Asbestos Disclosure Clause (Question #30)

The United States Consumer Produce Safety Commission has maintained that asbestos materials are hazardous if they release separate fibers which can be inhaled. Asbestos is a common insulation material on heating pipes, boilers, and furnaces. It may also be present in certain types of floor and ceiling materials, shingles, plaster products, cements and other building materials. The buyer may have the property professionally inspected for the presence of asbestos and if repair or removal of asbestos is desired, proper safety guidelines must be observed.

D. Lead Paint Disclosure (Question #31)

Whenever a child under six years of age resides in any residential premises in which any paint, plaster or other accessible material contains dangerous levels of lead, the owner is required by law to remove all said paint, plaster or cover with appropriate materials so as to make it inaccessible to a child under six years of age. Consumption of lead is poisonous and may cause serious personal injury. Whenever such residential premises containing dangerous levels of lead undergoes a change of ownership, and as a result a child under six years of age will become a resident, the new owner is required by law to remove said paint, plaster cover or encapsulate it with appropriate materials so as to make it inaccessible to such child. Buyer should receive information pamphlet from Department of Public Health.

F. Chlordane Disclosure Clause (Question #34b.)

Pesticide products containing chlordane were banned in Massachusetts on June 11, 1985, following a determination by the Department of Food and Agriculture that the use of chlordane may cause unreasonable adverse effects on the environment including risk of cancer. Although existing data do not conclusively prove that significant health effects have occurred as a direct result of chlordane use, the long-term potential health risks are such that it is prudent public health policy, according to the Department, to eliminate the further introduction of chlordane into the environment.

G. Mold Information (Question #33)

Molds are naturally occurring organisms that exist both indoors and outdoors. More than 1000 different kinds of mold have been found in homes in the United States. Molds are fungi that reproduce by making spores. Spores are small and lightweight and able to travel through the air. Molds need moisture and food to grow and their growth is stimulated by warm, damp and humid conditions. Molds can use materials such as wood, paper, drywall and carpet as food sources. Reducing dampness indoors is often key to reducing the growth of mold. Depending on the level of mold, allergies, respiratory problems and other health consequences can be triggered in sensitive individuals. However, exposure to mold does not always result in health problems. As of July 2002, U.S. governmental agencies reported that a determination had not been made what quantity of mold was acceptable in an indoor environment. For more information on mold, contact an engineer or other qualified mold inspector. Information may also be found at the web site for the U.S. Environmental Protection Agency, www.epa.gov.

H. Fair Housing Notice

It is unlawful to discriminate on the basis of race, color, religious creed, national origin, age, gender, sex, ancestry, marital status, veteran status, sexual orientation, disability, presence of a child, receipt of public assistance or other protected classification in the sale or rental of covered housing.

# XIII. Acknowledgment Seller(s) hereby acknowledges that the information set forth above is true and accurate to the best of his or her knowledge. Seller(s) agrees

to defend and indemnify the broker(s) and any subagents for disclosure of any information contained herein. Seller(s) acknowledges receipt of a copy of the Seller's Statement of Property Condition.

Date 9 27 25 Seller Seller

**BUYER'S INITIALS** 

SELLER'S INITIALS



#### **Unofficial Property Record Card - Haverhill, MA**

### **General Property Data**

Parcel ID 561-2-70 Account Number 561-2-70

Prior Parcel ID

Property Owner BENHAM WALTER M JR Property Location 23 ADELE AVE HAVERHILL

Property Use ONE FAM

Mailing Address 23 ADELE AVE Most Recent Sale Date 6/21/2019

Legal Reference 37605-605

**Basement Floor ASPHL TILE** 

**Heating Fuel GAS** 

Air Conditioning 0%

# of Full Baths 1

# of Bsmt Garages 0

**Heating Type FORCED H/W** 

City HAVERHILL Grantor PALMERI ROBERT A

Mailing State MA Zip 01830 Sale Price 310,000

ParcelZoning N/A Land Area 0.283 acres

#### **Current Property Assessment**

Card 1 Value Building Value 331,900 Stra Features Land Value 185,900 Total Value 518,300

#### **Building Description**

Building Style RANCH Foundation Type CONCRETE Flooring Type HARDWOOD

# of Living Units 1 Frame Type WOOD

Year Built 1962 Roof Structure GABLE

Building Grade AVERAGE Roof Cover ASPHALT

Building Condition N/A Siding VINYL

Finished Area (SF) 2524.40001 Interior Walls DRYWALL

Number Rooms 6 # of Bedrooms 3

# of 3/4 Baths 0 # of 1/2 Baths 0 # of Other Fixtures 0

### **Legal Description**

## **Narrative Description of Property**

This property contains 0.283 acres of land mainly classified as ONE FAM with a(n) RANCH style building, built about 1962, having VINYL exterior and ASPHALT roof cover, with 0 commercial unit(s) and 1 residential unit(s), 6 room(s), 3 bedroom(s), 1 bath(s), 0 half bath(s).

## **Property Images**



Disclaimer: This information is believed to be correct but is subject to change and is not warranteed.



## The Commonwealth of Massachusetts

Executive Office of Health and Human Services
Department of Public Health
Bureau of Environmental Health
250 Washington Street, 7th Floor
Boston, MA 02108
(800) 532-9571 / (617) 624-5757



# CHILDHOOD LEAD POISONING PREVENTION PROGRAM (CLPPP) PROPERTY TRANSFER LEAD PAINT NOTIFICATION

Under Massachusetts and federal law, this notification package must be given to prospective purchasers of homes built before 1978. This package must be given in full to meet state and federal requirements. It may be copied, as long as the type size is not made smaller. Every seller and any real estate agent involved in the sale must give this package before the signing of a purchase and sale agreement, a lease with an option to purchase, or, under state law, a memorandum of agreement used in foreclosure sales. Sellers and agents must also tell the prospective purchaser any information they know about lead in the home. They must also give a copy of any lead inspection report, risk assessment report, Letter of Compliance or Letter of Interim Control. This package is for compliance with both state and federal lead notification requirements.


Real estate agents must also tell prospective purchasers that under the state Lead Law, a new owner of a home built before 1978 in which a child under six will live or continue to live must have it either deleaded or brought under interim control within 90 days of taking title. This package includes a check list to certify that the prospective purchaser has been fully notified by the real estate agent. This certification should be filled out and signed by the prospective purchaser before the signing of a purchase and sale agreement, a lease with an option to purchase or a memorandum of agreement used in a foreclosure sale. It should be kept in the real estate agent's files. After getting notice, the prospective purchaser has at least 10 days, or longer if agreed to by the seller and buyer, to have a lead inspection or risk assessment if he or she chooses to have one, except in cases of foreclosure sales. There is no requirement for a lead inspection or risk assessment before a sale. A list of private lead inspectors and risk assessors licensed by the Department of Public Health is attached and can also be found on the Childhood Lead Poisoning Prevention Program's website at <a href="https://www.mass.gov/dph/clppp">www.mass.gov/dph/clppp</a>.

Sellers and real estate agents who do not meet these requirements can face a civil penalty of up to \$1,000 under state law; a civil penalty of up to \$10,000 and possible criminal sanctions under federal law, as well as liability for resulting damages. In addition, a real estate agent who fails to meet these requirements may be liable under the Massachusetts Consumer Protection Act.

The property transfer notification program began in 1988 and has been very successful. It provides information you need to protect your child, or your tenants' child, from lead poisoning. Massachusetts has a tax credit of up to \$1,500 for each unit deleaded. There are also a number of grants and no-interest or low-interest loans available for deleading. It's up to you to do your part toward ending lead poisoning.

PLEASE TAKE THE TIME TO READ THIS DOCUMENT. LEAD POISONING IS THE NATION'S LEADING ENVIRONMENTAL HAZARD AFFECTING CHILDREN. DON'T GAMBLE WITH YOUR CHILD'S FUTURE.

CLPPP Form 94-2, 6/30/94, Rev. 2/03, Rev. 10/09



# NEW ENGLAND RADON, LTD.

11A Industrial Way, Unit 3 Salem, New Hampshire 03079 603-893-4260

Fax: 603-893-8163

Email: <u>despinal@newenglandradon.com</u> Website: www.newenglandradon.com

RADON ANALYSIS

DATE:

05/14/2019

WALTER BENHAM

ABC H.I.

TEST SITE.

23 ADELE AVENUE, HAVERHIL, MA

EXPOSURE START: 20190510 AT 11:50 EXPOSURE STOP: 20190512 AT 19:30

CODE NUMBER	TEST RESULTS (pC/L)	TEST LOCATION
3765298 3765299 Average	2.3 2.3 2.3	CELLAR CELLAR

THIS READING IS BELOW THE EPA ACTION GUIDE LEVEL OF 4.0 PCI/L, A READING BELOW 4.0 PCI/L FOR YOUR SCREENING MEASUREMENT, IF MADE WITH THE HOUSE OR BASEMENT CLOSED-UP PRIOR TO AND DURING THE TESTING PERIOD (AS SPECIFIED IN THE INSTRUCTIONS) INDICATES THAT THERE IS RELATIVELY LITTLE CHANCE THAT THE RADON CONCENTRATION, IN THE LIVING AREAS, WILL BE GREATER THAN 4 PCI/L AS AN ANNUAL AVERAGE DUE TO AIRBORNE RADON SEEPING THROUGH THE BASEMENT.

(THIS READING IS VALID ONLY IF HOUSE CONDITIONS ARE MAINTAINED AS SPECIFIED FOR THE DURATION OF THE TEST. NEW ENGLAND RADON, LTD. CANNOT BE HELD LIABLE FOR ERRONEOUS READINGS IF APPROPRIATE HOUSE CONDITIONS ARE NOT MAINTAINED.)



# Certificate of Completion

JULY 2, 2019

WALTER BENHAM 23 ADELLE AVENUE HAVERHILL, MA 01832

This is to certify that Asbestos Abatement work, completed on the date listed below has been performed at the following address and dates:

#### RESIDENCE 23 ADELLE AVENUE HAVERHILL, MA 01832

The work has been reviewed and was found completed in a competent and professional manner.

- Required procedures specified in the contract documents and/or Federal and State laws and regulations have been strictly adhered to with respect to asbestos transportation and disposal at an approved landfill site.
- CONTRACTOR:
- LICENSE NUMBER:
- SITE SUPERVISOR
- CERTIFICATION NUMBER
- COMPLETION DATE

A-BEST ABATEMENT, INC. MA AC/000197, ME CF-0077 NH C-056, CT 000223 JAIME GARCIA MA 001191 NH 001591 JUNE 26, 2019 May 14, 2019

Walter Benham HOME OWNERS 2 9 Bartlet St. Ste 242

Andover, MA 01810

**Project Number:** 

Project Name: 23 Adele Ave., Haverhill, MA

Date Sampled:

2019-05-10

Work Received:

2019-05-10

Work Analyzed:

2019-05-13

Analysis Method:

BULK PLM ANALYSIS EPA/600/R-93/116

John brufted

FieldID	Material	Location	Color	Non-Asbestos %	Asbestos %	
LabID						
1	Mastic on FT	Basement Floor	black	Non-Fibrous 90	Detected	
473971					Chrysotile 10	
2	Floor Tile (Only)	Basement Floor	tan	Non-Fibrous 98	Detected	
473972		And the second s			Chrysotile 2	
3	Insulation	Attic	brown	Non-Fibrous 100	Detected	
473973					Tremolite < 1	

Tuesday 14 May 2019

Analyzed by:

**End of Report** 

Batch: 42544

Page 1 of 1

# CLEAResult'

## CONTRACT

CLEAResult 50 Washington Street, Wastborough, MA, 01581

Customer Name: WALTER BENHAM Email: wmbenham@outlook.com

Phone: 781-318-6640

Premise Address: 23 Adele Ave, Haverhill, MA 01832 Mailing Address: 23 Adele Ave, Haverhill, MA 01832

Project ID: 3886442 Date: Oct. 18, 2019

#### **Job Description**

Contractor will perform or cause to be performed the following work on these "Premises" in a professional manner and in accordance with the terms of this Contract, including the attached recommendations/work order describing the work in detail (the "Work") which are

Measure Description	Location	650-00			
Air Sealing at Estimated 62.5 CFM50 Per Hour		<u> (evenity</u>	(Uni)	ावावाल्या	@177707000TL
Bath Fan - Vent to Solfit	Other	12	hr	\$1,110.96	\$0.00
	Other	1	each	\$137.71	\$34.43
Exterior Door Weather Stripping (with AS hrs)	Other	3	each	\$90.21	
Door Sweep (with AS hrs)	Other	3	each		\$0.00
Door - 2" Thermal Barrier Polyiso	Other	1		\$75.93	\$0.00
Rim Joist - 6" Fiberglass Batting			each	\$90.44	\$22.61
Rim Joist - 2" Thermal Barrier Polyiso	Other	78	SF	\$210.60	\$52.65
Thermal Barrier Polyiso	Other	115	SF	\$549.70	\$137.42
				40.00.0	\$137.4

Total:

\$2,265.55

Program incentive:

-\$2,018.44

**Customer Total:** 

\$247.11

#### **Payment**

Customer agrees to pay Contractor for the Work, the Customer Share of the Contract Price as follows: Payment #1: \$82,00 as a Deposit payable to CLEAResult upon signing the Contract (not to exceed 1/3 of the total retail costs). Mail check & contract to CLEAResult, 50 Washington Street, . Westborough, MA, 01581. Final Payment: \$165,11 as the final payment for the Work shall be payable to the Home Performance Contractor (HPC) or Independent Installation Contractor (IIC) upon satisfactory completion of the Work. Customer understands that he/she will not be required to pay the Utility Incentive Share of the Contract price in the amount of \$2,018,44. Changes to individual line items and/or previous incentives may increase or decrease the size of the Utility Incentive Share.

#### **Dispute Resolution**

The IIC and Customer hereby mutually agree in advance that in the event that the IIC has a dispute concerning this Contract, the IIC may submit such dispute to a private arbitration service which has been approved by the Office of Consumer Affairs and Business Regulation and Customer shall be required to submit to such arbitration as provided in M.G.L. c 142A.